



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentees: James George Allen et al

Patent No. 7,093,544 B1

Issued: January 6, 2004

September 29, 2006

Title: Control Device For A Railroad Car

ATTN: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate

OCT 10 2006

of Correction

REQUEST FOR A CERTIFICATE OF CORRECTION

Dear Sir:

It is respectfully requested that a Certificate of Correction be issued in accordance with 35 U.S.C. 255 to correct the mistakes of Applicants as set forth on the enclosed Form PTO/SB/44.

The error in FIG. 1 is that it did not show passages 113A and 113B communicating as described in column 6, lines 54-57 (page 16, lines 10-13 of the application) and as shown in original FIG. 9 but not numbered. These numbers have been added to new FIG. 9. This is not new matter in view of both original FIG. 9 and the specification disclosing this communication.

Corrected FIG. 8 adds 53A to identify a passage in plate 31 as described in column 4, line 39 (page 10, line 24 of the application) and as shown in original FIG. 9. This is not new matter.

The error in column 3, line 60 is at page 9, line 6 of the application since the numeral 37 is not in FIG. 1, but is in FIG. 7.

10/04/2006 BABRAHA1 00000067 7093544

01 FC:1811

100.00 0P

The error in column 4, line 9 is at page 9, line 21 of the application since the numeral 31 is not in FIG. 2 but is in FIG. 1.


The error in column 5, line 34 is at page 13, line 4 of the application since the numeral 70 identifies a recess in lines 27 and 28, column 5 (page 12, lines 24 and 25 of the application) and line 28, column 5 (page 12, line 25 of the application) identifies a North pole piece 71.

The same error of "22" should be -- 20 -- is in each of column 6, line 54 (page 16, line 10 of the application), column 7, line 11 (page 17, line 6 of the application), and column 7, line 19 (page 17, line 14 of the application). The numeral 20 describes the coil in line 26, column 3 (page 7, line 25 of the application) while 22 identifies a diode in line 28, column 3 (page 8, line 1 of the application).

The other error in column 7, line 19 is at page 17, line 14 of the application. The second rail is identified as 19 in line 24, column 3 (page 7, line 21 of the application) whereas 14 identifies the first rail in line 25, column 3 (page 7, lines 22 and 23 of the application).

A check for \$100 for the certificate of correction fee is included.

Respectfully submitted,



859, 266-0169

Enc.

Frank C. Leach, Jr.
Attorney for Patentees
676 Mt. Vernon Drive
Lexington, Kentucky 40502

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: ATTN: Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on the date indicated below.

Date September 29, 2006

By Frank C. Leach, Jr.

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTIONPage 1 of 1

PATENT NO. : 7,093,544 B1

APPLICATION NO.: 10/751,620

ISSUE DATE : Aug. 22, 2006

INVENTOR(S) : James George Allen et al

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Delete FIGS. 1, 8, and 9 and substitute included FIGS. 1, 8, and 9

Col. 3, line 60, "37 and 39" should read -- 37 (see FIG. 7) and 39 (see FIG. 1) --

Col. 4, line 9, "31 has a flat, upper surface 46 (see FIG. 1)" should read -- 31 (see FIG. 1) has a flat, upper surface 46 --

Col. 5, line 34, "70" should read -- piece 71 --

Col. 6, line 54, "22" should be -- 20 --

Col. 7, line 11, "22" should be -- 20 --

Col. 7, line 19, "14" should be -- 19 --

Col. 7, line 19, "22" should be -- 20 --

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Frank C. Leach, Jr.
676 Mt. Vernon Drive
Lexington, KY 40502

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.




FIG. 1




FIG. 8




FIG. 9